

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page 1 of 3
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/02/2008
Test Type: Smoke	Ground Condition: Dry: X Damp: _ Wet: _	Supervisor: E.R. Crew: 04
Manhole ID: S19O__010MH	Test ID: 1029-582	Notifications Made: __X__ Residents, Fire, 311
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)		

[illegible]

**CITY OF BALTIMORE**  
**SMOKE TESTING OBSERVATION SUMMARY**  
**LOW LEVEL SEWERSHED**  
BALTIMORE CITY PROJECT 1029  
REI/DRAYCO

Unique Test ID: 582	Date: 09/02/2008	Basin: LL - 44	Manhole ID: S19O__010MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 621 S. BENTALOU ST.			
Source Type: 03 Service Line		Sector: 02 Private	
Location: 09 Yard - Side		Severity: 03 Moderate	Drainage Area: 5
Comments: SMOKE IS COMING FROM THE GROUND AROUND THE CLEANOUT CAP.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01  
Filename: 1029-582\_OB01-01.jpg